

# Monitoring of Mineral and Landfill Planning Permissions

## Report for Connon Bridge Landfill Site, East Taphouse, Liskeard on 9<sup>th</sup> September 2020



### Report Summary

### No. of Conditions

Development was not considered to be compliant with the condition at the time of the site monitoring visit. Furthermore it is considered that there is an urgent need to remedy this breach due to the potential risk and/or consequences to the environment or amenity. It is therefore concluded that steps should be undertaken without further delay to remedy this breach. Appropriate enforcement action is likely to be expedient should noncompliance with this condition continue.

0

Development was not considered to be compliant with the condition at the time of the site monitoring visit and/or there are outstanding matters which remain to be resolved at this time by the operator or this Authority. Any continued noncompliance or breach of this condition may result in the instigation of enforcement action.

0

Development was considered to be compliant with the relevant planning condition at the time of the site monitoring visit although some minor works may be required.

55